

Governor's Ranch Elementary School - Sampled 6/24/16			
CustomerSampleNumber	Description	Lead Result	Units
18200-115-S	Sink in Clinic	1.3	ppb
18200-119-S	Sink in Planning Room near Office	2.7	ppb
18200-137-S	Sink in Teacher's Lounge	1.2	ppb
18200-402-S1	Art Room Sink	4.6	ppb
18200-402-S2	Art Room Sink	10.4	ppb
18200-402-S3	Art Room Sink	2.5	ppb
18200-402-S4	Art Room Sink	4.0	ppb
18200-133H-DF	Hallway Drinking Fountain near Cafeteria	<0.1 *	ppb
18200-107-S1	Food Service-Hand Sink	8.2	ppb
18200-107-S2	Food Service-Wash/Rinse	16.4	ppb
18200-107-S3	Food Service-Rinse/Sanitize	5.7	ppb
18200-C-14X-S	Hallway Sink in C-Pod	2.4	ppb
18200-C-8H-DF	Hallway Drinking Fountain near Classroom C-305	1.2	ppb
18200-C-13H-DF	Hallway Drinking Fountain near Classroom C-301	0.8	ppb
18200-132-S	Sink in Library Workroom	1.3	ppb
18200-B-14X-S	Hallway Sink in B-Pod	1.5	ppb
18200-B-8H-DF	Hallway Drinking Fountain near Classroom B-205	5.1	ppb
18200-B-13H-DF	Hallway Drinking Fountain near Classroom B-201	1.6	ppb
18200-A-14X-S	Hallway Sink in A-Pod	0.8	ppb
18200-A-13H-DF	Hallway Drinking Fountain near Classroom A-107	0.8	ppb
18200-A-8H-DF	Hallway Drinking Fountain near Classroom A-103	0.6	ppb
18200-126H-DF	Hallway Drinking Fountain near Kindergarten Classroom A-101	0.3	ppb
18200-A-101-S	Sink in Kindergarten Classroom A-101	0.5	ppb
18200-A-101-SWB	Sink with Bubbler in Kindergarten Classroom A-101	0.7	ppb
18200-A-100-SWB	Sink with Bubbler in Kindergarten Classroom A-100	0.5	ppb
18200-A-100-S	Sink in Kindergarten Classroom A-100	0.5	ppb
18200-REC-104-DF	Drinking Fountain in Temp REC-104	0.8	ppb
18200-RE-027-DF	Drinking Fountain in Temp RE-027	1.6	ppb
18200-REC-081-DF	Drinking Fountain in Temp REC-081	1.9	ppb
18200-R1-167-DF	Drinking Fountain in Temp R1-167	5.9	ppb
18200-REC-081-S	Sink in Temp REC-081	1.2	ppb

* This result is less than 0.1 ppb, which is the lowest level that can be reported by the lab.