

Molholm Elementary School - Sampled 6/26/16				Resampled** 11/17/16	
CustomerSampleNumber	Description	Lead Result	Units	Lead Result	Units
28000-224-S	Sink in Counselor Office	3.3	ppb		
28000-145-S1	Food Service-Hand Sink	3.1	ppb		
28000-145-S2	Food Service-Wash/Rinse/Sanitize	3.5	ppb		
28000-04-SWB	Sink with Bubbler in Kindergarten Classroom 04	1.2	ppb		
28000-04-S	Sink in Kindergarten Classroom 04	0.5	ppb		
28000-06-SWB	Sink with Bubbler in Kindergarten Classroom 06	2.6	ppb		
28000-06-S	Sink in Kindergarten Classroom 06	1.0	ppb		
28000-08-SWB	Sink with Bubbler in Kindergarten Classroom 08	3.6	ppb		
28000-08-S	Sink in Kindergarten Classroom 08	1.2	ppb		
28000-10-SWB	Sink with Bubbler in Kindergarten Classroom 10	4.9	ppb		
28000-10-S	Sink in Kindergarten Classroom 10	11.8	ppb		
28000-09-SWB	Sink with Bubbler in Classroom 09	1.1	ppb		
28000-09-S	Sink in Classroom 09	0.8	ppb		
28000-07-SWB	Sink with Bubbler in Classroom 07	2.4	ppb		
28000-07-S	Sink in Classroom 07	0.9	ppb		
28000-05-SWB	Sink with Bubbler in Classroom 05	2.9	ppb		
28000-05-S	Sink in Classroom 05	0.6	ppb		
28000-03-SWB	Sink with Bubbler in Classroom 03	1.3	ppb		
28000-03-S	Sink in Classroom 03	0.3	ppb		
28000-GYM-DF	Drinking Fountain in Gym	11.6	ppb		
28000-131H-DFL	Hallway Drinking Fountain across from Workroom 205/Left	2.3	ppb		
28000-131H-DFR	Hallway Drinking Fountain across from Workroom 205/Right	3.2	ppb		
28000-205-S	Sink in Workroom 205	7.9	ppb		
28000-ART-S1	Art Room Sink	0.4	ppb		
28000-ART-S2	Art Room Sink	1.4	ppb		
28000-20-S1	Sink in Classroom 20	8.9	ppb		
28000-20-S2	Sink in Classroom 20	9.9	ppb		
28000-22-SWB	Sink with Bubbler in Classroom 22	4.6	ppb		
28000-22-S	Sink in Classroom 22	13.3	ppb		
28000-24-SWB	Sink with Bubbler in Classroom 24	2.3	ppb		
28000-24-S	Sink in Classroom 24	4.9	ppb		
28000-23-SWB	Sink with Bubbler in Classroom 23	9.6	ppb		
28000-23-S	Sink in Classroom 23	19.6	ppb	8.1	ppb
28000-21-S	Sink in Classroom 21	9.0	ppb		
28000-21-SWB	Sink with Bubbler in Classroom 21	16.0	ppb	4.0	ppb
28000-19-SWB	Sink with Bubbler in Office	4.5	ppb		
28000-19-S	Sink in Office	3.8	ppb		
28000-108H-DF	Hallway Drinking Fountain near Classroom 20	4.0	ppb		
28000-MUSIC-S	Sink in Music Room	9.0	ppb		
28000-210H-DFL	Hallway Drinking Fountain near Music Room/Left	0.9	ppb		
28000-210H-DFR	Hallway Drinking Fountain near Music Room/Right	3.0	ppb		
28000-213-S	Sink in Teacher's Lounge	3.8	ppb		
28000-220-S	Sink in Clinic	6.2	ppb		
28000-R1-171-S	Sink in PreK Temp R1-171	0.3	ppb		
28000-RE-050-SWB	Sink with Bubbler in PreK Temp RE-050	2.5	ppb		
28000-RE-050-S	Sink in PreK Temp RE-050	0.2	ppb		
28000-REC-064-S	Sink in Temp REC-064	0.2	ppb		
28000-R1-049-SWB	Sink with Bubbler in Temp R1-049	9.8	ppb		
28000-R1-049-S	Sink in Temp R1-049	0.7	ppb		
28000-R1-139-DF	Drinking Fountain in PreK Temp R1-139	15.5	ppb	Repairs Pending	
28000-REC-129-DF	Drinking Fountain in Temp REC-129	0.6	ppb		
28000-R1-146-DF	Drinking Fountain in Temp R1-146	3.8	ppb		
28000-R1-023-DF	Drinking Fountain in Temp R1-023	2.8	ppb		
28000-REC-128-S	Sink in Temp REC-128	< 0.1 *	ppb		

\* This result is less than 0.1 ppb, which is the lowest level that can be reported by the lab.

\*\* Resampling results after elevated fixtures were removed and replaced.