

Colorow Elementary School - Sampled 6/22/16			
CustomerSampleNumber	Description	Lead Result	Units
06000-110A-S	Sink in Clinic	2.9	ppb
06000-1002-H-DF	Hallway Drinking Fountain near Main Office	0.4	ppb
06000-165-S1	Food Service Sink-Wash/Rinse/Sanitize	5.2	ppb
06000-165-S2	Food Service Sink-Hand Sink	2.6	ppb
06000-149-S	Sink in Teacher's Lounge	0.5	ppb
06000-1006H-DF	Hallway Drinking Fountain near Teacher's Lounge	0.9	ppb
06000-179-S	Sink in Library Workroom	24.2	ppb
06000-404-S1	Sink in Classroom 404	25.6	ppb
06000-404-S2	Sink in Classroom 404	24.2	ppb
06000-1257H-DF	Hallway Drinking Fountain near Classroom 404	0.8	ppb
06000-1036H-DF	Hallway Drinking Fountain near Classroom 305	0.8	ppb
06000-304-S	Sink in Classroom 304	19.4	ppb
06000-131H-DF	Hallway Drinking Fountain near Library	<0.1 *	ppb
06000-129-S1	Art Room Sink	0.8	ppb
06000-129-S2	Art Room Sink	2.3	ppb
06000-1361H-DF	Hallway Drinking Fountain near Classroom 204	0.7	ppb
06000-203-S1	Sink in Classroom 203	6.2	ppb
06000-203-S2	Sink in Classroom 203	5.7	ppb
06000-1402H-DF	Hallway Drinking Fountain near Classroom 105	1.0	ppb
06000-104-S	Sink in Classroom 104	8.4	ppb
06000-1450-S	Sink in Kindergarten Classroom 1450	10.2	ppb
06000-1450-SWB	Sink with Bubbler in Kindergarten Classroom 1450	3.8	ppb
06000-1452-SWB	Sink with Bubbler in Kindergarten Classroom 1452	2.4	ppb
06000-1452-S	Sink in Kindergarten Classroom 1452	16.8	ppb
* This result is less than 0.1 ppb, which is the lowest level that can be reported by the lab.			