

Pleasant View Elementary School - Sampled 6/23/16				Resample Results	
CustomerSampleNumber	Description	Lead Result	Units	Lead Result	Units
33000-132-S	Sink in Clinic	4.5	ppb		
33000-135.2-DF	Drinking Fountain near Gym	<0.1 *	ppb		
33000-138-SWF	Sink with Filter in Teacher's Lounge	1.4	ppb		
33000-138-S	Sink in Teacher's Lounge	1.9	ppb		
33000-148-S1	Food Service Sink-Wash/Rinse/Sanitize	60.6	ppb	9.8	ppb
33000-148-S2	Food Service Sink-Hand Sink	5.3	ppb		
33000-145H-DF	Hallway Drinking Fountain near Computer Lab	3.9	ppb		
33000-221XH-DF	Hallway Drinking Fountain near Classroom 218	8.8	ppb		
33000-219-S	Sink in Classroom 219	8.7	ppb		
33000-219-SWB	Sink with Bubbler in Classroom 219	0.2	ppb		
33000-205-S	Sink in Classroom 205	2.6	ppb		
33000-205-SWB	Sink with Bubbler in Classroom 205	0.1	ppb		
33000-206-S	Sink in Classroom 206	4.5	ppb		
33000-206-SWB	Sink with Bubbler in Classroom 206	<0.1 *	ppb		
33000-209H-DF	Hallway Drinking Fountain across from Classroom 215	0.3	ppb		
33000-110-S	Sink in Kindergarten Classroom 110	3.2	ppb		
33000-110-SWB	Sink with Bubbler in Kindergarten Classroom 110	0.8	ppb		
33000-108-S	Sink in Classroom 108	5.5	ppb		
33000-108-SWB	Sink with Bubbler in Classroom 108	2.1	ppb		
33000-106-S	Sink in Classroom 106	1.0	ppb		
33000-106-SWB	Sink with Bubbler in Classroom 106	1.4	ppb		
33000-105-S	Sink in Classroom 105	2.9	ppb		
33000-105-SWB	Sink with Bubbler in Classroom 105	3.4	ppb		
33000-107-S	Sink in Classroom 107	3.7	ppb		
33000-107-SWB	Sink with Bubbler in Classroom 107	2.3	ppb		
33000-109-S	Sink in Kindergarten Classroom 109	6.2	ppb		
33000-109-SWB	Sink with Bubbler in Kindergarten Classroom 109	5.6	ppb		
33000-102-S	Sink in Classroom 102	1.3	ppb		
33000-100-S	Sink in Classroom 100	2.5	ppb		
33000-111-S	Sink in Pre-K Classroom 111	5.3	ppb		
33000-118H-DFL	Hallway Drinking Fountain near Music Room/Left	1.4	ppb		
33000-118H-DFR	Hallway Drinking Fountain near Music Room/Right	1.5	ppb		
33000-112-S1	Art Room Sink	16.6	ppb	2.9	ppb
33000-112-S2	Art Room Sink	3.0	ppb		
33000-112-S3	Art Room Sink	8.2	ppb		
* This result is less than 0.1 ppb, which is the lowest level that can be reported by the lab.					
** Resampling results after elevated fixtures were repaired, or removed and replaced. Resamples collected on 8/10/16 or 4/21/17.					