

Lumberg Elementary School - Sampled 6/29/16					Resampled 4/27/17 or 11/17/16	
SampleNumber	Description	Lead Result	Units	Lead Result	Unit	
24000-A128-S	Sink in Clinic	3.5	ppb	4.7	ppb	
24000-A127-S	Sink in Clinic Restroom	0.4	ppb	0.7	ppb	
24000-A130H-DFL	Hallway Drinking Fountain Near Gym/Left	0.3	ppb	0.3	ppb	
24000-A130H-DFR	Hallway Drinking Fountain Near Gym/Right	0.4	ppb	0.2	ppb	
24000-A109H-DFL	Hallway Drinking Fountain Near Cafeteria/Left	6.4	ppb	7.9	ppb	
24000-A109H-DFR	Hallway Drinking Fountain Near Cafeteria/Right	5.6	ppb	7.0	ppb	
24000-A102-S1	Food Services - Wash/Rinse Sink	1.6	ppb	1.9	ppb	
24000-A102-S2	Food Services - Sanitize Sink	2.4	ppb	4.4	ppb	
24000-A102-S3	Food Services - Food Prep Sink	2.2	ppb	1.8	ppb	
24000-23-SWB	Sink with Bubbler in Classroom 23	4.1	ppb	2.2	ppb	
24000-23-SWF	Sink with Filter in Classroom 23	6.8	ppb			
24000-21-SWB	Sink with Bubbler in Classroom 21	1.3	ppb	2.6	ppb	
24000-21-S	Sink in Classroom 21	5.7	ppb			
24000-MUSIC-SWB	Sink with Bubbler in Music Room	0.6	ppb	0.2	ppb	
24000-MUSIC-S	Sink in Music Room	0.6	ppb			
24000-ART-S1	Sink in Art Classroom/Left	17.6	ppb	0.4 **	ppb	
24000-ART-S2	Sink in Art Classroom/Right	6.5	ppb			
24000-20-SWB	Sink with Bubbler in Classroom 20	1.2	ppb	1.6	ppb	
24000-20-S	Sink in Classroom 20	7.9	ppb			
24000-B100H-DFL	Hallway Drinking Fountain Near Classroom 22/Left	0.9	ppb	0.7	ppb	
24000-B100H-DFR	Hallway Drinking Fountain Near Classroom 22/Right	1.2	ppb	1.2	ppb	
24000-22-S1	Sink in Classroom 22/Left	1.4	ppb			
24000-22-S2	Sink in Classroom 22/Right	1.8	ppb			
24000-A112-S	Sink in Teacher's Lounge	2.0	ppb	0.4	ppb	
24000-D104H-DFL	Hallway Drinking Fountain Near Classroom 05/Left	1.2	ppb	0.8	ppb	
24000-D104H-DFR	Hallway Drinking Fountain Near Classroom 05/Right	1.0	ppb	0.1	ppb	
24000-14-SWB	Sink with Bubbler in Classroom 14	4.6	ppb	3.6	ppb	
24000-14-S	Sink in Classroom 14	2.0	ppb			
24000-16-SWB	Sink with Bubbler in Classroom 16	0.7	ppb	1.8	ppb	
24000-16-S	Sink in Classroom 16	2.9	ppb			
24000-18-SWB	Sink with Bubbler in Classroom 18	4.9	ppb	5.4	ppb	
24000-18-S	Sink in Classroom 18	2.1	ppb			
24000-19-SWB	Sink with Bubbler in Classroom 19	0.3	ppb	0.5	ppb	
24000-19-S	Sink in Classroom 19	3.4	ppb			
24000-C111H-DFL	Hallway Drinking Fountain Near Classroom 17/Left	3.7	ppb	2.8	ppb	
24000-C111H-DFR	Hallway Drinking Fountain Near Classroom 17/Right	1.3	ppb	1.3	ppb	
24000-17-SWB	Sink with Bubbler in Classroom 17	0.7	ppb	1.1	ppb	
24000-17-S	Sink in Classroom 17	4.0	ppb			
24000-15-S	Sink in Classroom 15	2.9	ppb			
24000-15-SWB	Sink with Bubbler in Classroom 15	2.6	ppb	0.9	ppb	
24000-D108H-DFL	Hallway Drinking Fountain Near Classroom 11/Left	3.0	ppb	0.6	ppb	
24000-D108H-DFR	Hallway Drinking Fountain Near Classroom 11/Right	4.0	ppb	0.6	ppb	
24000-R1-190-DF	Drinking Fountain in Temporary Kindergarten Classroom R1-190	1.4	ppb	1.2	ppb	
24000-R1-190-S	Sink in Temporary Kindergarten Classroom R1-190	1.4	ppb			
24000-R1-172-DF	Drinking Fountain in Temporary Classroom R1-172	1.0	ppb	1.0	ppb	
24000-R1-140-DF	Drinking Fountain in Temporary Classroom R1-140	5.1	ppb	8.9	ppb	
24000-R1-140-S	Sink in Temporary Classroom R1-140	4.9	ppb			
24000-R1-196-DF	Drinking Fountain in Temporary Classroom R1-196	0.4	ppb	0.4	ppb	
24000-R1-028-DF	Drinking Fountain in Temporary Classroom R1-028	5.4	ppb	4.1	ppb	
24000-R1-175-DF	Drinking Fountain in Temporary Classroom R1-175	7.3	ppb	7.4	ppb	
24000-13-S	Sink in Classroom 13	<0.1 * †	ppb			
24000-11-S	Sink in Classroom 11	0.2 †	ppb			
24000-11-SWB	Sink with Bubbler in Classroom 11	0.2 †	ppb	0.1	ppb	
24000-A118-S	Sink in Kitchen area Lounge	8.0 †	ppb	10.0	ppb	

* This result is less than 0.1 ppb, which is the lowest level that can be reported by the lab.

** Resampled on 11/17/16 after elevated fixtures were removed and replaced.

† This fixture was sampled for the first time on 11/17/16.